

# **Fusion Clear glazing system**

#### 1. Glazing:

- 1.1 To be cleaned using an approved and suitable glass cleaning agent. Apply a fine spray of solution and wipe down with a paper towel.
- 1.2 Avoid cleaning on wet silicon or glass ends where the fusion dry joint is to be applied.
- 1.3 Glass cleaning agent should not be removed using a sharp implement. Avoid over applying the cleaning agent.

### 2. Window Manifestation:

- 2.1 After application we recommend Manifestation is left for 48 hours before cleaning, this will allow time for adhesive to fully cure.
- 2.2 Use warm soapy water with a lint free cloth and squeegee.
- 2.3 DO NOT use abrasive cleaners or strong detergents.

## 3. Fusion framework:

- 3.1 Wipe down using warm soapy water and a damp cloth.
- 3.2 DO NOT clean with any other cleaning agents, abrasive papers or sharp implements.



### 4. Free hanging blinds:

- 4.1 Wipe down using warm soapy water and a damp cloth.
- 4.2 Small Vacuum dust brush.
- 4.3 DO NOT clean with any other cleaning agents, abrasive papers or sharp implements.

### 5. Doors/Ironmongery

- 5.1 Follow instructions in Glazing section 1 and Window Manifestation section 2 for cleaning of glass pivoting doors, sliding doors and over panels.
- 5.2 Sliding door "Slide" sign to be applied by glaziers. Site project Manager to confirm the glaziers have applied the sign.
- 5.3 Sliding door stops and sliding gear should be checked annually and retightened by suitable Allen Key as necessary.
- 5.4 Timber door hinges to be lightly oiled and checked quarterly
- 5.5 Glass/timber door handles should be checked quarterly, and retightened by suitable Allen Key as necessary.
- 5.6 Overhead door closers to be checked quarterly with the arm joint to be lightly oiled, (tighten if necessary)

General cleaning is recommended on a daily basis to remove dust and finger marks.

Annual and Quarterly checks to be undertaken as specified.

